VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5452	DATE	Feb. 8 2024	
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation			
DESCRIPTION OF DEFECT	On some heavy-duty trucks equipped with a 6R20 engine, the lubrication performance of the adjusting screws for the exhaust rocker arms is insufficient, and the adjusting screws may prematurely wear out or break by prolonged idling operations, causing noise or a decrease in output. If the vehicle continues to be used in this condition, the valve bridges may fall and cause damage to the engine. In the worst case, the vehicle may become unable to run.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FS70HZ		2022 ~ 2023	140
2KG-FS74HZ		2022~2023	85
2KG-FU70HY		2022~2023	2
2KG-FU74HZ		2022~2023	42
2KG-FV70HJR		2023 ~ 2023	57
2KG-FV70HX		2022~2023	276
2KG-FV70HY		2022~2023	84
2KG-FV70HYP		2023 ~ 2023	22
2KG-FV70HZ		2022~2023	82
2KG-FV70HZP		2023~2023	5
2KG-FV74HJR		2022~2023	16
2PG-FP74HDR		2023~2023	378
2PG-FP74HER		2023 ~ 2023	139
2PG-FP74HGR		2023 ~ 2023	12
2PG-FS70HZ	「FUSO SUPER GREAT」	2022~2023	39
2PG-FS74HY		2022~2023	36
2PG-FS74HZ		2022~2023	971
2PG-FS75HZ		2022~2023	136
2PG-FU70HY		2022~2023	30
2PG-FU74HY		2022~2023	32
2PG-FU74HZ		2022~2023	372
2PG-FU75HZ	-	2022~2023	104
2PG-FV70HX		2022~2023	254
2PG-FV70HY		2022~2023	90
2PG-FV70HZ		2022~2023	102
2PG-FV74HJR		2023~2023	2
2PG-FV74HZ		2022~2023	78
2PG-FY70HY		2022~2023	34
2PG-FY74HY		2022~2023	22
		TOTAL	3,642

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
2RG-FP74HDR	「FUSO SUPER GREAT」	2018~2020	2	
2RG-FP74HER		2018~2020	5	
2PG-FS74HZ		2017~2020	3	
2PG-FU70HY		2019	1	
2PG-FV70HX		2019~2021	4	
2PG-FV70HY		2019	1	
2PG-FV74HZ		2020	1	
2KG-FV70HJR		2018~2020	3	
		TOTAL	20	

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	REMARKS
6R20 Engine Assy	6R20021221 6R20021231 6R20022281 6R20030321 6R20040405 6R20041401 6R20041405 6R20042411	$2022{\sim}2023$	11	
		TOTAL	11	