

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5467	DATE	Mar. 26 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some electric light-duty trucks, the VCU control program is inappropriate, and it may incorrectly determine that a communication error has occurred and shut down the high-voltage system for safety. As a result, the high-voltage battery charge rate displayed in the meter will show 0% at an unexpected time while the driver is driving, making the vehicle no longer able to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-FEAVK	「FUSO eCANTER」	2023～2024	978
ZAB-FEB8K		2023～2024	48
ZAB-FEBVK		2023～2023	3
ZAB-FEC9K		2023～2023	2
ZAB-FED9K		2023～2023	20
		TOTAL	1,051