

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5510	DATE	July.5,2024
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to insufficient validation during development, there is a possibility that the battery may excessively move and the fixing device may come off in the event of a rear-end collision, resulting in the battery not being held in its designated position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BF-S403P	Gran Max	2020-2023	322
5BF-S413P			237
5BF-S403U	Town Ace		12,706
5BF-S413U			5,576
5BF-S403F	Bongo		2,689
5BF-S413F			1,086
		TOTAL	22,616