

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5525	DATE	July 25, 2024
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the transmission control module, due to an improper program to control the clutch system during deceleration, when making stop with hard breaking, the clutch connecting an engine with electric motor may be disengaged. Therefore, the engine power cannot translate into the traction force, causing an inability to start moving even when the accelerator pedal is depressed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-KH3R3P	Mazda 「CX-60」	2022-2024	9,422
		Total	9,422