

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 5 4 5	DATE	Oct. 3. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the electric control unit (body control module), the lighting time of the automatic lock function operation lamp does not meet the safety standard due to the improper control program.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2021~2023	8, 155
ZAA-SNFE0		2022~2023	2, 907
6AA-GFC28	SERENA	2023~2024	47, 966
6AA-GC28			5, 306
5BA-FC28		2022~2024	23, 034
5BA-FNC28			5, 257
5BA-C28			3, 873
5BA-NC28		2023~2024	1, 841
6AA-E13			5, 810
6AA-SNE13			861
		TOTAL	105, 010