

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | 5 5 5 8 | DATE | Oct. 24. 2024 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | In the PTC heater that assists heating, if the heater is repeatedly used in a state where the heater is operating at maximum output due to improper control, the PTC heater harness connector terminal may be deformed due to the heat generated by the PTC heater. Therefore, if the terminal part continues to be used as it is, the terminal part becomes hot due to poor contact, the connector may melt, and in the worst case, it may lead to a thermal incident. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|--------------------------|--|---------------------------|-----------------------|
| LDF-VW2E26 | NISSAN NV350 CARAVAN CARAVAN | 2012~2021 | 3, 163 |
| LDF-VW6E26 | | | 25, 573 |
| LDF-CW4E26 | | | 449 |
| LDF-CW8E26 | | | 9, 070 |
| LDF-DW4E26 | | | 290 |
| CBF-CS8E26 3BF-CS8E26 | | 2017~2023 | 1, 155 |
| CBF-DS8E26 | | 2018~2021 | 435 |
| LDF-JVW2E26 | ISUZU COMO | 2012~2020 | 58 |
| LDF-JVW6E26 | | 2012~2021 | 348 |
| LDF-JCW4E26 | | 2012~2020 | 6 |
| LDF-JCW8E26 | | 2012~2021 | 66 |
| | | TOTAL | 40, 613 |