VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5652	DATE	May. 21. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain electric parking brakes, due to an inappropriate program in the ECU, the ECU may not start up when the start switch is turned on. This may cause the warning light to come on and the parking brake to become unable to be released or activated.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-XED100V	「DUTRO Z EV」	2022~2024	1, 221
ZAB-XED100			
XED100	Γ– <u>J</u>	2021	1
		TOTAL	1, 222