

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5670	DATE	Jun.26 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>Due to inappropriate control programs in the BMS and DCB, it may be falsely determined that a CAN communication error has occurred. As a result, the EV system warning light (red) may come on, and the high-voltage battery charge rate displayed in the meter may indicate 0%, making driving impossible, or the high-voltage system may become unable to start when the key is turned on.</p> <p>*BMS (Battery Management System: an ECU for high-voltage battery)</p> <p>*DCB (DC Box: an ECU for fast charging)</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-FEAVK	「FUSO eCANTER」	2023～2024	1,764
ZAB-FEB8K		2023～2024	92
ZAB-FEBVK		2023～2024	8
ZAB-FEC9K		2023～2024	3
ZAB-FED9K		2023～2024	27
		TOTAL	1,894