

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5743	DATE	December 4, 2025
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In the manual sliding door, the design of the door stopper was inappropriate. Therefore, if the sliding door is opened forcefully, the door stopper may deform. Continuing to use it in this condition may cause the deformation to gradually increase, and in the worst case, the sliding door could get stuck beyond the door stopper, making it impossible to close the sliding door.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S700V 5BD-S700V	HIJET ATRAI		125,621
3BD-S710V 5BD-S710V			71,096
3BD-S700W	HIJET DECKVAN ATRAI DECKVAN		2,360
3BD-S710W			3,386
3BD-S700M 5BD-S700M	PIXIS VAN	2021-2025	16,275
3BD-S710M 5BD-S710M			9,563
3BD-S700B 5BD-S700B	SAMBAR		3,195
3BD-S710B 5BD-S710B			3,254
		TOTAL	234,750