

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5797	DATE	Mar. 30 2026
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>The engine warning lamp (MIL) does not light up in the event of a urea water pump rotation sensor fault, due to insufficient ACM software design considerations. Therefore, it does not meet safety regulations.</p> <p>(ACM: After Treatment System Control Module)</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FS70HZ	「FUSO SUPER GREAT」	2021 ~ 2023	602
2KG-FS74HZ		2021 ~ 2023	509
2KG-FU70HY		2021 ~ 2023	15
2KG-FU74HZ		2021 ~ 2023	208
2KG-FV70HJR		2021 ~ 2024	501
2KG-FV70HX		2021 ~ 2023	1,815
2KG-FV70HY		2021 ~ 2023	394
2KG-FV70HYP		2021 ~ 2024	157
2KG-FV70HZ		2021 ~ 2023	400
2KG-FV70HZIP		2021 ~ 2024	37
2KG-FV74HJR		2021 ~ 2025	55
2KG-FV80VJR		2024 ~ 2026	164
2KG-FV80VYP		2024 ~ 2025	63
2KG-FV80VZP		2024 ~ 2025	6
2KG-FV84VJR		2024 ~ 2026	19
2PG-FP74HDR		2021 ~ 2025	2,499
2PG-FP74HER		2021 ~ 2024	1,000
2PG-FP74HGR		2021 ~ 2024	158
2PG-FP84HDR		2024 ~ 2026	419
2PG-FP84HER		2024 ~ 2026	87
2PG-FP84HGR		2024 ~ 2026	47
2PG-FS70HZ		2021 ~ 2024	322
2PG-FS74HY		2021 ~ 2024	106
2PG-FS74HZ		2021 ~ 2026	7,358
2PG-FS75HY		2021 ~ 2023	4
2PG-FS75HZ		2021 ~ 2026	1,347
2PG-FS80HZ		2024 ~ 2026	55
2PG-FS80VZ		2024 ~ 2025	94
2PG-FS84HY		2025 ~ 2025	14
2PG-FS84HZ		2024 ~ 2026	1,360

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS84VY	「FUSO SUPER GREAT」	2024 ~ 2025	15
2PG-FS84VZ		2024 ~ 2026	2,435
2PG-FS85HZ		2024 ~ 2026	318
2PG-FS85VZ		2024 ~ 2026	323
2PG-FU70HY		2021 ~ 2024	203
2PG-FU74HY		2021 ~ 2024	178
2PG-FU74HZ		2021 ~ 2025	2,280
2PG-FU75HZ		2021 ~ 2024	740
2PG-FU80HY		2024 ~ 2025	40
2PG-FU80VY		2024 ~ 2026	20
2PG-FU84HY		2024 ~ 2026	32
2PG-FU84HZ		2024 ~ 2026	425
2PG-FU84VY		2024 ~ 2025	8
2PG-FU84VZ		2024 ~ 2026	498
2PG-FU85HZ		2024 ~ 2026	68
2PG-FU85VZ		2024 ~ 2026	158
2PG-FV70HX		2021 ~ 2024	1,578
2PG-FV70HY		2021 ~ 2024	522
2PG-FV70HZ		2021 ~ 2024	457
2PG-FV74HJR		2021 ~ 2024	34
2PG-FV74HZ		2021 ~ 2024	462
2PG-FV80HX		2024 ~ 2026	265
2PG-FV80HY		2024 ~ 2025	117
2PG-FV80HZ		2024 ~ 2026	92
2PG-FV80VX		2024 ~ 2026	336
2PG-FV80VY		2024 ~ 2026	185
2PG-FV80VZ		2024 ~ 2026	182
2PG-FV84HZ		2024 ~ 2026	70
2PG-FV84VZ		2024 ~ 2026	71
2PG-FY70HY		2021 ~ 2024	192
2PG-FY74HY		2021 ~ 2026	203
2PG-FY80HY		2024 ~ 2025	31
2PG-FY80VY		2024 ~ 2026	22
2PG-FY84HY		2024 ~ 2026	38
2PG-FY84VY		2024 ~ 2026	11
2RG-FP84VDR		2024 ~ 2026	1,013
2RG-FP84VER		2024 ~ 2026	618
2RG-FP84VGR		2024 ~ 2025	28
2RG-FV84VJR		2024 ~ 2026	9
			TOTAL