

KU-KEN-107

No. TCD-452-1

Date March 9, 1967

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: NAMC YS-11

2. Compliance required as indicated

Revise subparagraph 2.1 (3), TCD-452, dated January 25, 1967 as follow.

(3) At the position of "door full open" the hook shall stand back more than 0.5 millimeter (0.02 inch) but less than 1.0 millimeter (0.04 inch) from the guide. More than 1.0 millimeter (0.04 inch) may be allowed provided it does comply with (a) and (b), A(3) of paragraph 2 of NAMC Alert Service Bulletin A32-63 (Rev 3).

3. Remarks:

3.1 Effective date: April 1st, 1967

3.2 NAMC Alert Service Bulletin A32-63 (Rev 3) covers this subject.