VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2734	DATE	March 31 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty sight seeing buses equipped with a toilet specifyed for cold district, due to improper installation work, the electric wire of the heater for the water can be pinched under the tank resulting in a short-circuit of the wiring and smokes at ceiling board if the worst comes.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PKG-RU1ESAJ	ISUZU GALA	2009-2010	14
LKG-RU1ESBJ		2010	1
		TOTAL	15