

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1845	DATE	May 22, 2012
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation )		
DESCRIPTION OF DEFECT	Height of FUP(Front Under run Protection) installed at the front part of cab does not comply with the safety regulation concerned.  Extension of FUP needs to be installed in order to meet the height with the regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unspecified	FH	2011	7
		TOTAL	7