

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1872	DATE	Sep 21, 2012
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Vehicles equipped with an automatic transmission are equipped with an exhaust system with less than optimal clearance to the transmission skid plate. If debris collects in this area and is not removed, the debris may contact the exhaust catalyst and cause afire without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JK38L	Jeep Wrangler Unlimited	2010	776
ABA-JK38S	Jeep Wrangler	2010	44
		Total	820