

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import Vehicles~~

CAMPAIGN No.	gai-1868	DATE	Sep 21th , 2012
MANUFACTURE	LBCE : Link-Belt Construction Equipment Company (Japanese importer : Hitachi Sumitomo Heavy Industries Construction Crane Co.,Ltd.)		
DESCRIPTION OF DEFECT	As the pressure gauge of the axles which indicates the internal pressure of the container for the breaking device in the vehicle driver's cabin does not have the mark of minimum effective operation pressure level, these vehicles are in non-conformant with road transport vehicle safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	STX700-2	2011-2012	2
	STX700L-2	2010-2012	3
		TOTAL	5