

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3015	DATE	Aug.16.2012
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy and medium duty trucks, the defective wheel bearings installed to the front axle of some trucks. If the vehicle is operated under the condition continuously, it can become shaky. In the worst case, a brake lining is dragged and fire may break out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FW1EBBG	HINO Profia	2012	3
LKG-FW1EBBJ		2011～2012	17
LKG-FW1EWBA		2011～2012	382
LKG-FW1EXBG		2011	3
LKG-FW1EXBJ		2011	2
LKG-FW1EYBG		2011～2012	56
LKG-FW1EYBJ		2011～2012	29
LKG-FW1EYCG		2011～2012	8
LKG-FW1EZBG		2011～2012	11
LKG-FW1EZBJ		2011～2012	10
LKG-FW1AXBG	HINO Ranger	2011～2012	16
LKG-FE7JEAA		2011～2012	61
LKG-FE7JGAA		2011～2012	43
LKG-FE7JJAA		2011～2012	44
LKG-FE7JJAAKAI		2011～2012	10
LKG-FE7JKAA		2011～2012	17
LKG-FE7JKAG		2011～2012	4
LKG-FE7JLAA		2011～2012	3
LKG-FE7JLAG		2011～2012	3
LKG-FE7JLAGKAI		2011～2012	6
LKG-FE7JMAA		2011～2012	13
LKG-FE7JMAG		2011～2012	8
LKG-FE7JPAA		2011～2012	12
LKG-FE7JPAAKAI		2011～2012	2
LKG-FE7JPAG		TOTAL	763
LKG-FE7JUAA			
LKG-FE7JUAG			
LKG-FJ7JDAA			
LKG-FJ7JEAA			
LKG-FJ7JGAA			
LKG-FJ7JHAA			
LKG-FJ7JJAA			
LKG-FJ7JKAA			
LKG-FJ7JKAG			
LKG-FJ7JLAA			
LKG-FJ7JLAG			
LKG-FJ7JNAA			
LKG-FJ7JNAAKAI			
LKG-FJ7JSAA			
LKG-FJ7JSAAKAI			