

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4204	DATE	1st-Mar-2018
MANUFACTURER	Alna Yano Special Purpose Vehicle Co, Ltd 1273 Muraida Maibara-City, Shiga 521-0231 Japan		
DESCRIPTION OF DEFECT	In the rear underrun protective device which got the type approval, several components and mounting position of the stay were different from those specified by the type approval. In addition, there were blanks and omission of seal by the quality control officer in the record table. For this reason, the device does not satisfy requirement for type approval and does not comply with the safety standards of the Road Trucking Vehicle Law.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-NMR85AN	ELF	2012	1
TPG-NMR85AN		2015	2
TRG-NMR85AN		2015	1
TKG-NPR85YN		2015	2
QDF-KDY231	DYNA	2013	1
CBF-SQ2F24	ATLAS	2012~2017	3
SDG-SZ5F24		2013~2014	3
SKG-SZ2F24		2012	1
SKG-TZ2F24		2012~2013	2
TKG-SZ2F24		2013~2016	2
TKG-SZ5F24		2016	1
TKG-AMR85AN		2012	1
TKG-XZC600M	DUTRO	2012~2014	2
TKG-XZC605M		2012	3
TKG-XZC645M		2015	1
TKG-XZU605M		2014	2
TQG-XKU605M		2012	1
PA-FE70DB	CANTER	2012	1
TKG-FEA50		2014~2015	2
TQG-FEA53		2012	1
TKG-BSZ2F24	CANTER GUTS	2015	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TKG-LHR85AN	TITAN	2012~2014	20	
TPG-LHR85AN		2015	2	
TRG-LHR85AN		2015~2017	6	
TKG-LHS85AN		2012~2013	2	
TRG-LHS85AN		2017	1	
TKG-LJR85AN		2013~2014	6	
TKG-LLR85AN		2014	1	
TRG-LLR85AN		2016~2017	5	
TKG-LMR85AN		2012~2013	4	
TRG-LMR85AN		2015~2016	5	
			TOTAL 86	