

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Vehicles

CAMPAIGN No.	4209	DATE	Mar. 5th, 2018
MANUFACTURER	Yokohama Sharyo Kogyo Co.,Ltd.		
DESCRIPTION OF DEFECT	In the backlight of the tractor, the geometric visibility of the lower part at the reverse lamp does not conform to the safety standards of the road carriage due to the mounting position of the rear number frame is inappropriate.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-FP64VDR	SUPER GREAT	2017	3
TOTAL			3