

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4207	DATE	March 8, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the combination meter, due to inappropriate communication program, communication signal cannot be transmitted /received. The error message about system including advanced smart city brake support may be displayed on the multi information display and the system may not operate. Also, the view of camera may not be displayed on the center display when customers try to change to the view of camera. Therefore, the driver may not be able to see the condition of the front and left side of the vehicle and this may not satisfy the safety standard		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-KG2P	Mazda「CX-8」	2017	966
		Total	966