

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2678	Date	June 27, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper chrome coating on rear brake calipers, chemical reaction between metal surface of the piston and brake fluid can cause oxidation which creates vapor gas. When brake line is filled with the gas, brake performance can decrease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-16CZD	The Beetle 1.4/110kW	2018	2
DBA-16CBZ	The Beetle 1.2/77kW	2018	157
		Total	159