

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	4285	DATE	June 27, 2018
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	<p>On a line of an intercooler system on a wheel crane, a bracket for fixing of a tube would be cracked by vibration of the engine, due to improper design of the bracket.</p> <p>At the worst case, the tube would be come off. Then it will cause decreasing of engine output by intake air amount shortage, and increasing of harmful exhaust gas amount.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CM03	MK650	2014-2018	5 units
CM03L	MK650	2014-2018	15 units
TOTAL			20