

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4313	DATE	19 SEP. 2018
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In radiator hose of agricultural chemical spraying vehicle, there are some defective products assembled, coolant may leak from the hose. Therefore, if it continue to be use, in the worst case, due to the lack of coolant, the engine overheats and it may be impossible to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	SSA- α 605	2018	59
	SSA- α 1005		
	SSA-V602		
	SSA-V1002		
		TOTAL	59