

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4360	DATE	October 30 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>Regarding the heavy-duty trucks equipped with compressed natural gas engines (CNG), if liquid which contains chlorine such as snow melting agent should adhere to the main stop valves installed on the fuel pipes, the main stop valves may be cracked. If the users keep driving their vehicles with cracked stop valves without repair, the cracks may widen and eventually result in fuel leakage.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QFG-CYJ78B	[GIGA]	2017-2018	4
QFG-CYL78B		2016-2018	8
		TOTAL	12