

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2746	DATE	November.1, 2018
MANUFACTURER	HONDA OF THE UK MANUFACTURING LTD.		
DESCRIPTION OF DEFECT	In vehicle equipped with pop-up hood system, right/left hood hinges or hood of wrong specifications may have been assembled under improper instructions concerning right/left hood hinges and hood assembly work. In this case, the system cannot fully raise the rear portion of the hood in a collision with a pedestrian and could, in the very worst case, fail to meet the pedestrian head and leg protection standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-FK7	「CIVIC」	2017	1,079
		TOTAL	1,079