

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4403	DATE	December 20,2018
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	<p>Regarding the front cylinder for opening and closing the cargo body of wing type of van truck, if the wing repeatedly open and close, there is possibility that cracks occur on the mounting part because of the strength poverty of mounting part of the bottom bracket of the cylinder.</p> <p>Therefore, if the wing open and close repeatedly in that state, the said mounting part of bracket will break, and there is possibility that the wing will not be able to open and close.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CD5CA	QUON	2017~2018	555
2PG-CG5CA	QUON	2017~2018	1156
2PG-CG5CE	QUON	2018	1
2PG-CYJ77C	GIGA	2017~2018	1123
2PG-CYJ77CA	GIGA	2017~2018	10
2PG-CYL77C	GIGA	2017~2018	306
2PG-FS74GZ	SUPER GREAT	2018	1
2PG-FS74HZ	SUPER GREAT	2017~2018	432
2PG-FU74HZ	SUPER GREAT	2017~2018	138
2PG-FW1AHG	PROFIA	2017~2018	549
2PG-FW1EHG	PROFIA	2017~2018	36
2RG-FW1AHG	PROFIA	2018	7
TOTAL			4314