

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4 4 4 1	DATE	Feb. 12. 2019
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	Due to an improper jig shape to assemble component parts to ABS (Anti-lock Brake System), some aluminum chips could occur during assembly process. Therefore, if such an aluminum chip is jammed in check-valve mechanism while ABS operates the front or rear tire could lock in.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZR900B	Z900	2019	70	
2BL-ZR900C	Z900RS	2019	748	
	Z900RS CAFE	2019	245	
TOTAL			1063	