

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	4451	DATE	February 19 ,2019
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		On individual specification spare wheel carriers of medium-duty trucks, weld points may have the possibility of cracking by inappropriate welding operation. In the case of an impact, vibrations may lead to rupture followed by fall-off of the spare wheel carriers and result in obstruction to road safety.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FTR90S2	“FORWARD”	2016	5
		TOTAL	5