

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2788	DATE	March 28. 2019	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to the braking system for heavy-duty tractor pole trailer specification, due to inappropriate modification method which is adding air supply ports (coupling) for pole trailers, the compressed air volume in the brake system may become insufficient and, upon sudden brake operations, the compressed air supply to the trailer may be delayed momentarily. Thus, the vehicle may not comply with the Japan Safety Regulations Article 12 (Braking system standard).			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
FH	Unspecified	2014-2018	52	Pole tractor specification
		TOTAL	52	