

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4458	DATE	April 2, 2019
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to inadequate design of the exhaust pipe , the straw debris may be accumulated between the exhaust pipe and the body frame, posing a fire hazard.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C519	「ER575」	2013~2017	422
YDN-C521		2017~2018	219
WDP-C518	「ER590」	2013~2017	655
WDP-C613	「ER6100」	2013~2017	767
WDR-C612	「ER6120」	2013~2017	1,470