

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2828	DATE	19 <sup>th</sup> April 2019
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	. The clutch cable may contact the main harness sheath potentially causing damage to the wiring within the main harness.		

EBL-GJ900	STREET TWIN	2015-2017	600
	T100	2016-2017	246
	STREET CUP	2016-2017	156
2BL-DGJ900	STREET TWIN	2017-2018	155
	T100	2017-2018	148
	STREET SCRAMBLER	2016-2018	334
	STREET CUP	2017-2018	67
EBL-HJ1200	T120	2016-2017	566
2BL-DHJ1200	T120	2017-2018	222
TOTAL			2,429