

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2829	DATE	19 th April 2019
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The coolant hose between the radiator and expansion tank may have been incorrectly routed during assembly.		

2BL-DHJ1200	Speed Twin	2019	53
		TOTAL	53