

第4号様式 (英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4502	DATE	May, 27, 2019
MANUFACTURER	Fuji Car Manufacturing Co., Ltd. 13-1 Chishiro-cho, Moriyama-city, Shiga, 524-0034, Japan		
DESCRIPTION OF DEFECT	Regarding of the garbage truck with sprinkler system, for the protective fuses is selected inappropriately, An overcurrent flows when a defect such as short circuit occurs, in the worst case, the wiring coating is melted, and in the result, there is a risk that smoking and firing could be happened.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NFG-NMR82N	Isuzu Elf	2008	1
BKG-NMR85AN		2009	1
TKG-NMR85N		2013	1
TPG-NKR85N		2018	1
BKG-BKR85AN	Nissan Desel Condor	2007~2008	3
PB-MK35AEH		2006	1
BDG-MK36CEH		2008	1
BDG-XZU304X	Hino Dutro	2009	1
SKG-XZU700M		2011	1
TKG-XZU700M		2012	1
KK-FD1JEEA	Hino Ranger	2003	1
ADG-FD7JEWA		2006	1
BDG-FD7JEWA		2009	4
		TOTAL	18

(日本工業規格A列4番)

備考 不具合箇所が複数ある場合であって対象車が異なる場合には、それを区別して記載すること。