

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2847	Date	May 29, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to the control program of the combination meter is inappropriate, if an abnormality occurs in the brake system, the warning light does not operate, and there is a possibility that the problem can not be recognized.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-16CBZ	The Beetle1.2/77kW	MY2019	1,020
ABA-16CZD	The Beetle1.4/110kW	MY2019	408
ABA-16CPL	The Beetle2.0T	MY2019	173
		Total	1,601