## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN NO.	4507	DATE	June 4 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The subject matter relates to a large rear reflector installed on medium-duty trucks. Because some of the said reflectors are inappropriately mounted, a geometric visibility of the said reflector may not conform to safety standards in the Road Transportation Vehicle Law.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SKG-FSR90S2 SPG-FSR90S2 SPG-FSR90T2 2PG-FSR90S2 2RG-FSR90S2 2RG-FSR90T2	[FORWARD]	2014-2019	405
		TOTAL	405