

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4520	DATE	Jun. 26. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>① On certain light-duty trucks, due to the improper instructions for the attachment of the labels indicating the kind of brake fluid, the label may not be attached. Therefore, these vehicles fail to comply with the requirements of Safety Standard article 12, Braking System Standard.</p> <p>② On certain rear axle housings of light-duty trucks, because the welding process work is improper, the flanges of the housing ends may be welded in an inclined position. Therefore, the center of rotation shifts, which may cause the rear axle shaft and the bearing to be fractured, resulting the vehicle to stop operating.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
NBG-BZU600M	[HINO Dutro]	2017~2019	276	①276 ②23
TSG-XKC605M		2017~2019	65	①65 ②5
TSG-XKC645M		2017~2019	35	①35 ②5
TSG-XKC655M		2017~2018	36	①36 ②2
TSG-XKU600M TSG-XKU600X		2017~2019	105	①105 ②18
TSG-XKU605M		2017~2019	30	①30
TSG-XKU640M		2017~2018	7	①7
TSG-XKU645M		2018~2018	3	①3
TSG-XKU650M		2017~2019	74	①74 ②3
TSG-XKU655M		2017~2019	26	①26 ②2
TSG-XKU700M		2017	19	①19
TSG-XKU702M		2017~2019	26	①26 ②4
TSG-XKU710M		2017~2018	136	①136

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TSG-XKU712M	[HINO Dutro]	2017~2019	228	①228 ②17
TSG-XKU720M		2017~2018	27	①27 ②1
TSG-XKU722M		2017~2019	30	①30 ②2
TKG-XZC600M		2017~2019	1,847	①1,847
TKG-XZC605M TKG-XZC605Y TPG-XZC605M TPG-XZC605Y		2017~2019	3,941	①3,941
TKG-XZC610T TPG-XZC610T		2017~2019	2,293	①2,293
TKG-XZC630T TPG-XZC630T		2017~2019	184	①184
TKG-XZC645M TPG-XZC645M		2017~2019	622	①622
TKG-XZC655M TPG-XZC655M		2017~2019	989	①989
TKG-XZC675M TKG-XZC675T		2017~2019	431	①431 ②50
TKG-XZC710M TPG-XZC710M		2017~2019	717	①717 ②31
2KG-XZU600F TKG-XZU600E TKG-XZU600M TKG-XZU600T TKG-XZU600X TPG-XZU600E TPG-XZU600M TPG-XZU600X		2017~2019	5,721	①5,721 ②281
TKG-XZU602F		2017~2019	166	①166 ②11
TKG-XZU605M TPG-XZU605M		2017~2019	4,941	①4,940 ②141
TKG-XZU610T TPG-XZU610T		2017~2019	656	①656 ②45
TKG-XZU620T TPG-XZU620T		2017~2019	3,993	①3,987 ②272

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TKG-XZU630T	[HINO Dutro]	2017~2019	739	①739 ②39
2KG-XZU640F TKG-XZU640M TPG-XZU640M		2017~2019	597	①596 ②39
TKG-XZU642F TPG-XZU642F		2017~2019	331	①331 ②15
TKG-XZU645M TPG-XZU645M		2017~2019	989	①989 ②98
2KG-XZU650F TKG-XZU650M TPG-XZU650M		2017~2019	1,322	①1,322 ②64
TKG-XZU652F TKG-XZU652M		2017~2019	447	①447 ②23
TKG-XZU655M TPG-XZU655M		2017~2019	2,606	①2,606 ②186
TKG-XZU675M TKG-XZU675T		2017~2019	2,347	①2,347 ②96
TKG-XZU685M		2017~2019	1,593	①1,590 ②99
TKG-XZU695M		2017~2019	678	①678 ②51
2KG-XZU700M 2KG-XZU700X TKG-XZU700M TPG-XZU700M		2017~2019	1,640	①1,633 ②46
TKG-XZU702M TPG-XZU702M		2017~2019	274	①274 ②19
2KG-XZU710M TDG-XZU710M TKG-XZU710M TPG-XZU710M		2017~2019	3,035	①3,033 ②176
TDG-XZU712M TKG-XZU712M TPG-XZU712M		2017~2019	3,772	①3,772 ②236
2KG-XZU720M TDG-XZU720M TKG-XZU720M TPG-XZU720M		2017~2019	1,656	①1,656 ②81

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TDG-XZU722M TKG-XZU722M TPG-XZU722M	[HINO Dutro]	2017~2019	2,320	①2,320 ②161
2KG-XZU730M		2017~2019	258	①258 ②6
TDG-XZU732M		2017~2019	157	①157 ②6
TKG-XZU775M		2017~2019	430	①430 ②44
NBG-BZU600 NBG-BZU600A		[Toyota Dyna200] [Toyota Dyna300]	2017~2019	99
TSG-XKC605	[Toyota Dyna400] [Toyota ToyoaceG25]	2017~2019	55	①55
TSG-XKC645	[Toyota ToyoaceG35] [Toyota ToyoaceG45]	2017	1	①1
TSG-XKC655		2017	1	①1
TSG-XKU600 TSG-XKU600A		2017~2018	5	①5
TSG-XKU605		2017~2018	12	①12
TSG-XKU650		2017~2019	141	①141
TSG-XKU655		2017~2018	10	①10
TSG-XKU700		2017~2018	9	①9
TSG-XKU702		2017	1	①1
TSG-XKU710		2017~2018	22	①22 ②2
TSG-XKU712		2017~2019	17	①17
TSG-XKU720		2017	16	①16
TSG-XKU722		2017~2018	6	①6
TKG-XZC600		2017~2019	1,778	①1,778

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TKG-XZC605 TKG-XZC605V TPG-XZC605 TPG-XZC605V	[Toyota Dyna200] [Toyota Dyna300] [Toyota Dyna400] [Toyota ToyoaceG25]	2017~2019	2,762	①2,762
TKG-XZC610D TPG-XZC610D	[Toyota ToyoaceG35] [Toyota ToyoaceG45]	2017~2019	246	①246
TKG-XZC630D TPG-XZC630D		2017~2019	27	①27
TKG-XZC645 TPG-XZC645		2017~2019	292	①292
TKG-XZC655 TPG-XZC655		2017~2019	215	①215
TKG-XZC675 TKG-XZC675D		2017~2019	546	①546 ②45
TKG-XZC710 TPG-XZC710		2017~2019	145	①145 ②9
2KG-XZU600W TKG-XZU600 TKG-XZU600A TKG-XZU600D TKG-XZU600H TPG-XZU600 TPG-XZU600A TPG-XZU600H		2017~2019	482	①482 ②27
TKG-XZU602W		2017~2018	8	①8 ②3
TKG-XZU605 TPG-XZU605		2017~2019	2,234	①2,234 ②20
TKG-XZU610D TPG-XZU610D		2017~2019	77	①77 ②5
TKG-XZU620D TPG-XZU620D		2017~2019	605	①605 ②27
TKG-XZU630D		2017~2019	85	①85 ②3
TKG-XZU640 TPG-XZU640		2017~2019	91	①91 ②1
TKG-XZU642W		2017	1	①1
TKG-XZU645 TPG-XZU645		2017~2019	537	①537 ②31

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
TKG-XZU650 TPG-XZU650	[Toyota Dyna200] [Toyota Dyna300]	2017~2019	141	①141 ②7
TKG-XZU652	[Toyota Dyna400] [Toyota ToyoaceG25]	2017~2019	11	①11
TKG-XZU655 TPG-XZU655	[Toyota ToyoaceG35] [Toyota ToyoaceG45]	2017~2019	875	①875 ②52
TKG-XZU675 TKG-XZU675D		2017~2019	546	①546 ②40
TKG-XZU685		2017~2019	376	①376 ②25
TKG-XZU695		2017~2019	418	①418 ②29
2KG-XZU700 2KG-XZU700A TKG-XZU700 TPG-XZU700		2017~2019	129	①129 ②1
TKG-XZU702 TPG-XZU702		2017~2019	46	①46
2KG-XZU710 TDG-XZU710 TKG-XZU710 TPG-XZU710		2017~2019	1,057	①1,057 ②74
TDG-XZU712 TKG-XZU712 TPG-XZU712		2017~2019	653	①653 ②38
2KG-XZU720 TDG-XZU720 TKG-XZU720 TPG-XZU720		2017~2019	339	①339 ②11
TDG-XZU722 TKG-XZU722 TPG-XZU722		2017~2019	857	①857 ②41
2KG-XZU730		2017~2019	50	①50
TDG-XZU732		2017~2019	59	①59 ②2
TKG-XZU775		2017~2019	206	①206 ②10
		TOTAL	69,104	①69,084 ②2,910

Vehicle which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
BKG-XZU304X	[HINO Dutro]	2011	1	②1
BKG-XZU348M		2011	1	②1
TKG-XZU620T		2016	1	②1
TKG-XZU655M		2016	1	②1
TKG-XZU685M		2016	1	②1
KK-XZU411	[Toyota Dyna300]	2000	1	②1
SKG-XZU710	[Toyota Dyna200]	2011	1	②1
SKG-XZU655		2011	1	②1
TDG-XZU720	[Toyota Dyna300]	2013	1	②1
		TOTAL	9	

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	REMARKS
Rear axle assembly	42110-37211	2018	1	②
	42110-37350		1	
	42110-37670		1	
	42110-37A00		1	
		TOTAL	4	