

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4549	DATE	August 22 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The software for users of the digital tachograph has inappropriate screen display programs, and consequently the device model identification number of the digital tachograph does not appear on the screen of an electronic file storage device, a condition not conforming to the safety regulations for tachograph in the Road Transport Vehicle Act of Japan.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CXY77BJ QPG-CXY77BJ	[GIGA]	2016-2017	4
2KG-CXY77CJ		2017	1
QKG-CXZ77BT QPG-CXZ77BT		2016-2017	9
2PG-CXZ77CT		2017	3
2KG-CYG60CM		2017	1
QKG-CYH77B		2016	2
QKG-CYJ77B QPG-CYJ77B		2015-2017	8
2KG-CYJ77C 2PG-CYJ77C		2017	32
QKG-CYL60B		2016	1
QKG-CYL77B QPG-CYL77B		2015-2017	29
2PG-CYL77C		2017	4
2PG-CYL77CM		2017	1
QKG-CYM77B		2017	1
QKG-CYM77BM		2017	1
2PG-CYM77C		2017	1
2KG-CYM77CM 2PG-CYM77CM		2017	10

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CYY77B	[GIGA]	2015-2017	4
QKG-CYY77BJ		2016	1
2KG-CYY77CY		2017	1
QDG-CYZ52BV		2016	1
QKG-CYZ77B		2017	1
QKG-CYZ77BJ QPG-CYZ77BJ		2017	2
QKG-CYZ77BM		2015-2017	4
2KG-CYZ77CM		2017	1
QKG-EXD52BD		2017	2
QPG-EXD77BG		2017	2
TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2 2PG-FRR90S2 2PG-FRR90T2 2RG-FRR90S1 2RG-FRR90S2 2RG-FRR90T2		[FORWARD]	2015-2017
TKG-FRS90S2	2017		1
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2 2PG-FSR90S2 2PG-FSR90T2 2RG-FSR90S2 2RG-FSR90T2	2015-2017		2,074
SKG-FSS90S2 SPG-FSS90S2 2PG-FSS90S2 2RG-FSS90S2	2015-2017		93
QKG-FTR34S2 QKG-FTR34T2 QPG-FTR34S2 QPG-FTR34T2	2015-2017		610

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FTR90S2 LKG-FTR90T2 LPG-FTR90S2 LPG-FTR90T2 2PG-FTR90U2 2PG-FTR90V2 2RG-FTR90U2 2RG-FTR90V2	[FORWARD]	2015-2017	2,107
QKG-FTS34S2 QPG-FTS34S2		2015-2017	7
2PG-FTS90S2		2017	2
QKG-FVR34U2 QPG-FVR34U2		2015-2017	74
2PG-FVR90U2		2017	4
QDG-FVZ34U2 QKG-FVZ34U2		2015-2017	338
2RG-BRR90T2	[CONDOR]	2017	1
2RG-BSR90S2 2RG-BSR90T2		2017	3
		TOTAL	5,901

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
User Software for Digital Tachograph.	1-87831532-0	2015-2017	180
	1-87831532-1	2016-2017	38
	1-87831533-1	2016-2017	11
	5-87832358-0	2015-2016	314
	5-87832358-1	2016-2019	112
	5-87832396-1	2018-2019	15
	8-98293877-0	2014-2019	528
	8-98293877-1	2015-2019	7
		TOTAL	1,205