VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2925	DATE	2019/9/26			
MANUFACTURE	Daimler AG					
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)					
DESCRIPTION OF	Daimler AG has determined that on certain GLE vehicles (167 platform) the air conditioning					
DEFECT drain hoses might be incorrectly fitted in the vehicle. In this case, condensation wat the air conditioning might enter the passenger compartment. If condensation water enters into the driver and passenger side footwells, it might condensation water enters into the driver and passenger side footwells.						
						ents installed in this area. This
						condition would increase the risk of fire due to a short circuit.
	In addition, the performance of other features of the vehicle could be impacted such as the					
	automatic emergency call (eCall) might not be available, the vehicle might not be able to be					
	unlocked and/or started and the engine limp-home mode might be activated during driving.					
	This increases the potential ri	sk of injury or a crash.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5AA-167159	GLE450 4MATIC	2019	160
		TOTAL	160