VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	4589	DATE	October 25 ,2019
MANUFACTURER	NIPPON TREX CO.,	LTD.	
DESCRIPTION OF			
DEFECT	Regarding the center axle type full trailer, strength of the connection part between drawbar and main rail is insufficient because of inappropriate strength design. Therefore, cracks may occur due to the burden at the time of running, and in the worst case, there is possibility that the said part breaks and the vehicle not be able to continue to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FCA217AD	-	2017	2
FCA220AA	-	2017	2
FCA226AA	—	2016	2
FCA227AA	—	2018	1
FCH226AB	—	2015	17
FCW223AA	—	2017	2
FCW227AC	—	2016	1
FCW227AD	_	2017	2
		TOTAL	29