

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2941	DATE	Oct. 30, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Marking of the aluminum wheel was not defined correctly. The letter "J" was forgotten at that. The aluminum wheel must be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-FYDAXS	Audi Q5 45Tq	2018	171
		Total	171