

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5434	D A T E	Jan.26. 2024
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	<p>In the impeller (resin impeller) of the fuel pump, since the molding conditions are inappropriate, the resin density may be low, and it may swell and deform with the fuel. Therefore, when the impeller comes in contact with the pump case, the fuel pump becomes malfunctioning, and in the worst case, there is a risk of engine stalling during running.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GT7	「XV」	2017 – 2019	35,930
DBA-GT3		2017 – 2019	16,612
5AA-GTE		2018 – 2019	8,436
5BA-SK9	「Forester」	2018 – 2019	22,210
5AA-SKE		2018 – 2019	20,161
DBA-SJ5		2017 – 2018	12,635
DBA-SJG		2017 – 2018	2,262
DBA-GT2	「Impreza」	2017 – 2019	12,954
DBA-GT7		2017 – 2019	11,260
DBA-GT3		2017 – 2019	8,814
DBA-GT6		2017 – 2019	7,484
DBA-GK7		2017 – 2019	4,313
DBA-GK6		2017 – 2019	2,693
DBA-GK2		2017 – 2019	2,155

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK3	「Impreza」	2017 – 2019	1,851
DBA-VM4	「Levorg」	2017 – 2020	22,631
DBA-VMG		2017 – 2019	6,890
DBA-BS9	「Legacy」	2017 – 2019	11,599
DBA-BN9		2017 – 2019	3,288
DBA-VAG	「WRX」	2017 – 2019	6,024
DBA-ZC6	「BRZ」	2017 – 2019	1,930
4BA-ZC6		2019	587
DBA-ZN6	「86」	2017 – 2019	5,449
4BA-ZN6		2019	1,675
		TOTAL	229,843

Parts shipped as repair parts that could have been assembled and the vehicle identified.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-SJG	「Forester」	2012 – 2017	59
DBA-SJ5		2012 – 2017	51
DBA-VM4	Levorg	2014 – 2016	50
DBA-VMG		2014 – 2017	30
DBA-ZC6	BRZ	2012 – 2017	64
DBA-BRG	Legacy	2012 – 2013	21
DBA-BMG		2012 - 2013	13

Parts shipped as replacement repair parts that could have been assembled and the vehicle identified.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BS9	「Legacy」	2016	1
DAA-GPE	「XV」	2013 – 2015	31
DBA-GT7		2017	1
DBA-GT7	「Impreza」	2017	3
DBA-GT3		2016 – 2017	3
DBA-GT6		2017	2
DBA-GT2		2016 – 2017	2
DBA-GK7		2017	2
DBA-GK6		2017	1
DAA-GPE		2015	1
DBA-VAG		「WRX」	2014 – 2017
TOTAL			343

Parts shipped as repair parts that could have been assembled but the vehicle cannot be identified.

PARTS	PARTS NUMBER	SHIPMENT PERIOD	NUMBER OF PARTS
「PUMP ASSY FUEL」	42021CA010	2017 – 2019	401
	42021SG060		147
	42021SG080		129
	42021SG070		101
	42021AJ210		66

Parts shipped as repair parts that could have been assembled but the vehicle cannot be identified.

PARTS	PARTS NUMBER	SHIPMENT PERIOD	NUMBER OF PARTS
「PUMP ASSY FUEL」	42021FL010	2017 – 2019	6
	42021FL030	2018 – 2019	6
	42021FL000		5
	42021SG020	2017 – 2018	5
	42021FL040	2018 – 2019	4
「PUMP WITH FILTER」	42022CA000	2017 – 2019	303
	42022AJ140		18
	42022SG000		15
	42022SG010		6
	42022FL010		4
	42022FL000		4
	42022FL030	2018	1
		TOTAL	1,221

Vehicles assembled with repair parts will undergo the same improvements.