

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5 4 4 8	DATE	February,21,2024
MANUFACTURE	Showa Aircraft Industry Co., Ltd.		
DESCRIPTION OF DEFECT	<p>There is a case of the Tank semi-trailer which has a brake tube was found improperly and insecurely attached. This instance may also cause interference between the brake tube and the unloading pipe.</p> <p>Therefore, there is a possible risk of damage if it is continuously driven. The brake tube may cause air leakage which could lower the control power. Furthermore, if the air leakage increases, it could potentially trigger a parking brake device set in operation, and at the worst scenario, moving while the brake in parking position may cause fire from the friction.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Showa ST20A	—	2017 – 2023	105
ST20A kai			55
Showa ST24A			101
ST24A kai			447
Showa ST30A kai			86
		TOTAL	794