

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 6 1 6	DATE	Sep.30.2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	The diaphragm in the braking booster was damaged when it was assembled. If the vehicle continues to be driven in this condition, the flaw may go through diaphragm. In an extreme case, the operating efforts of the brake pedal increase and the brake stopping distance might get longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ADF-VWE25	CARAVAN	2 0 1 0	8
CBF-VRE25			1
		TOTAL	9