

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2651	DATE	November 19, 2010
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO.,LTD (JAPAN)		
DESCRIPTION OF DEFECT	Rear brake pipe during assembly of the brake system, there is something improper adjustment of the brake pipe and the brackets of mounting. Therefore, the users use to continued, the pipe has to cracked then oil leak.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-CFB	ZX145W-3	2008-2010	23
TOTAL			23