

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2685	DATE	Jan, 11 , 2011
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO.,LTD 6-1-45 Koshienguchi Nishinomiya-city Hyogo-pref. Japan		
DESCRIPTION OF DEFECT	The spring hanger installation plate may interfere and damage the inner side tire in case of driving over a curb and so on due to the unsuitable clearance setting between the said plate and the tires of the bulk tank cement tanker trailer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KA2465	Pneumatic bulk tank semi-trailer	2006~2007	14
KA2365A	Pneumatic bulk tank semi-trailer	2006~2007	13
KA2265AH	Pneumatic bulk tank semi-trailer	2006	2
KA3365U	Pneumatic bulk tank semi-trailer	2007	1
KA2865	Pneumatic bulk tank semi-trailer	2007	1
TOTAL			31