

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2702	DATE	February 3 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the street cleaning trucks, it has been found that a valve installed on an exhaust pipe outlet port to keep rainwater from entering was secured in an inadequate way, and therefore, the valve securing fittings may come off by exhaust pressure. Thus, if it is used as is, there is a possibility that the parts may be dropped.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-FRR90T2(kai)	FORWARD	2007-2008	32
PDG-FTR34T2(kai)		2007-2009	29
PKG-FTR34T2(kai)			
PDG-FVR34U2(kai)		2007-2009	11
		TOTAL	72