

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2710	DATE	Feb.15,2011
MANUFACTURER	YUSOKI KOGYO CO.,LTD. 102 KAMIHAMA-CHO HANDA AICHI,475-8668 JAPAN		
DESCRIPTION OF DEFECT	The axles used for semi-trailers do not have enough room of strength for the various use situation. This condition might cause crack by long-term use to the spindle of the axle. Therefore, as a result, the axle might be broken in occasion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YFS2101A		10001~10030 Sep.11,1994~Oct.23,1994	30
YFS220A		10046~10049 Oct.1,1994~Oct.2,1994	4
YFS220AAB		10095 Sep.29,1994	1
YFS220AC		10185~10190 Nov.27,1994~Nov.28,1994	6
YFS220AD		10123~10127 Nov.29,1994~Nov.30,1994	5
YFS220AAG		10307 Jan.16,1995	1
YFS220AAF		10313・10393・10394 Jan.24,1995~Feb.26,1995	3
YFS2201改		10328・10707 Jan.30,1995~Jun.18,1995	2
TS1911		1911001~1911003 Jun.8,1995~Jun.10,1995	3
TS2103		21030114~21030160 Jun.11,1995~Mar.10,1996	14
TS2107		2107001~2107003 Nov.10,1994~Nov.12,1994	3
		TOTAL	72