

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>2690</b>	<b>DATE</b>	<b>January 27, 2011</b>
<b>MANUFACTURER</b>	<b>FURUKAWA UNIC CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	On truck mounted cranes, the cable pathway for the parking brake does not have enough clearance between the transmission cross member and the body bolt. As a result, the parking brake cable in question rubs against the cross member and body bolt. If the cable pathway continues to be used in this state, this will damage the outer housing on said parking brake cable and obstruct the movement of the central line, and the parking brake will be rendered inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FRR90G3S	Isuzu Forward	2005~2007	14
ADG-FRR90H3S		2005~2007	19
ADG-FRR90J3S		2005~2007	116
ADG-FRR90K3S		2005~2009	361
ADG-FRR90L3S		2005~2007	52
		TOTAL	562