VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2820	DATE	16 . Sept. 2011		
MANUFACTURER	HITACHI	CONSTRUCTION MACHINERY CO, LTD.			
DESCRIPTION OF	There is something of the common rail which is a part of fuel system is insufficiency. Therefore, If the machine is used continuously, there is possibility that the common rail will crack, and then worst, fuel will leak.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
SD-HS56	Z W 2 2 0	2005-2006	15	
JDS - HS 5 6		2007-2008	19	
SD-HS57	Z W 2 5 0	2006	1	
JDS - HS 5 7		2007-2009	4	
SD - S56	Z W 2 2 0	2005-2007	23	
JDS - S56		2007-2009	56	
SD - S57	Z W 2 5 0	2005-2006	6	
JDS - S57		2007-2009	19	
		TOTAL	143	