

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	2 8 2 7	DATE	21, September, 2011
MANUFACTURER	Kobelco Construction Machinery Co., Ltd.		
DESCRIPTION OF DEFECT	<p>Plug for air bleeding is equipped in main Hydraulic Line in order that air bleeding and pressure adjustment job after filling hydraulic oil can be performed easily on production line at factory.</p> <p>Inner Seal for Plug will occasionally be damaged while the machine is working. Continuing to use the machine on such condition, Hydraulic oil will leak at that Plug so much that it will cause the difficulty of travelling at worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CH02	HK350W	2003 ~ 2004	5
TOTAL			5