

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2824	DATE	Sep.27.2011
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the welfare vehicles for commercial use equipped with an electrical sliding door, a necessary empty space between the platform and the rear seating position, which is prescribed in the aisle requirement of Safety Regulation Section 23.2, is not secured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-TRH200K "kai"(modified)	HIACE REGIUS ACE	2004-2011	187
KR-KDH200K "kai"(modified)		2005-2007	22
KR-KDH205K "kai"(modified)		2004-2007	9
ADF-KDH201K "kai"(modified) LDF-KDH201K "kai"(modified)		2007-2011	16
ADF-KDH206K "kai"(modified) LDF-KDH206K "kai"(modified)		2008-2011	25
		TOTAL	259